

9 March 2015

Mr Peter Law  
Technical Manager  
Wesbeam Pty Ltd  
PO Box 217  
**WANNEROO WA 6496**

Dear Peter

**Re: Testing of Wesbeam LVL Scaffold Planks**

This note is to confirm that the EWPA has completed an extensive testing program on your Laminated Veneer Lumber Scaffold Planks. Testing has included both untreated LVL Scaffold Planks and Scaffold Planks preservative treated to Hazard Class 3 in accordance with AS/NZS 1604.4.

Testing was performed in accordance with AS/NZS 1577:2013 to requirements for "heavy duty" ratings and have included all properties listed in the Standard. A summary of results are detailed in Table One.

Yours sincerely



Simon Dorries  
**GENERAL MANAGER**  
**EWPA**

**TABLE ONE: Summary of Test Results**

<b>Property from AS/NZS 1577</b>	<b>Treatment</b>	<b>Test Result - Per AS/NZS 1577</b>
Strength @ 2 x working load (Heavy Duty Loadings)	Nil	Pass
	H3 LOSP Treated	Pass
Stiffness @ Heavy Duty Loadings	Nil	Pass
	H3 LOSP Treated	Pass
Sliding Test	Nil	Pass
	H3 LOSP Treated	Pass
Slip Test	Nil	Pass
	H3 LOSP Treated	Pass